



Featuring
E123 Technology
Ball Mark Retrieval System

THE STEP BY STEP PROCESS


Acculinx



DIVOT MADE BY BALL FLIGHT



REPAIR DIVOT



SLIDE MARK OFF FOR
BALL PLACEMENT

AUTOMATING BALL MARK RETRIEVAL PROCESS

E123 TECHNOLOGY



1ST, PLACE TURF REPAIR
FORK INSIDE POCKET



2ND, PICK UP MARK AND
PLACE INSIDE POCKET



3RD, RETRIEVE TURF REPAIR
FORK AND BALL MARK
AUTOMATICALLY LINKED
TOGERTHER AT NEXT HOLE